

**BLACKSTONE RIVER BASIN
WORCESTER, MASSACHUSETTS**

**GREEN HILL POND DAM
MA 00149**

**PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM**



NEW ENGL

1979
PERMANENT

The original hardcopy version of this report
contains color photographs and/or drawings.
For additional information on this report
please email

U.S. Army Corps of Engineers
New England District
Email: Library@nae02.usace.army.mil

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00149	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Green Hill Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE July 1979
		13. NUMBER OF PAGES 65
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Blackstone River Basin Worcester, Mass.		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Green Hill Pond Dam is an earthfill embankment 200 feet long and 20 feet high with a stone masonry core wall 17 feet high. Generally the dam is in good condition although the outlets to the spillway and overflow diversion are in poor condition. Green Hill has been classified in the "high" hazard category. There is potential hazard at the site. An inflow test flood of 280 cfs will overtop the main dam by an average of 0.2 feet.		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

JUN 18 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:


I am forwarding to you a copy of the Green Hill Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, City of Worcester, Department of Public Works, 30 East Worcester Street, Worcester, Massachusetts 01604, ATTN: Mr. F. Worth Landers, Commissioner.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

NEDED-E

6 July 1979

Mr. F. Worth Landers, Commissioner
Department of Public Works
City of Worcester
20 East Worcester Street
Worcester, MA 01604

Dear Commissioner Landers:

Inclosed for your use are three copies of the Green Hill Pond Phase I, Inspection Report as requested in your telephone conversation of 26 June with Mr. James of this office. Should you have any questions concerning this report we suggest you contact the Commonwealth of Massachusetts, Department of Environmental Quality Engineering first; then, if there are further questions contact the Project Management Branch, Engineering Division of this office.

Since these reports are in limited supply, we are requesting that upon completion of your review you return two (2) reports to this office in the pre-addressed envelope. Your cooperation in this matter is greatly appreciated.

Sincerely yours,

Incl
As stated

JOE B. FRYAR
Chief, Engineering Division

CF: Mr. Gould ✓
Eng Div Files

GREEN HILL POND DAM

MA 00149

BLACKSTONE RIVER BASIN
WORCESTER, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION
PROGRAM

NATIONAL DAM INSPECTION
PROGRAM

PHASE I INSPECTION REPORT

BRIEF ASSESSMENT

Identification No.: MA00149

Name of Dam: Green Hill Pond

Town: Worcester

County and State: Worcester County, Massachusetts

Stream: Hermitage Brook - Tributary of the Blackstone
River

Date of Inspection: July 31, 1978

Green Hill Pond Dam, which was originally built around 1850, was reconstructed about 1881. The dam is an earthfill embankment 200 feet long and 20 feet high with a stone masonry core wall 17 feet high. The spillway is an ungated overflow weir with a vertical discharge shaft which is located near the midpoint of the dam. The weir is 23.6 feet long with an elevation (El) of 651.0 at the crest. The ungated outlet conduit from the spillway is 573 feet long. It consists of an 18-inch diameter reinforced concrete pipe which connects to a 30-inch diameter reinforced concrete pipe. There is an overflow diversion structure located at the northeast end of the pond. The outlet conduit for the overflow is 30-inch diameter reinforced concrete pipe. The inlet to the diversion has an elevation of 650.9. Due to downstream pipe sizes and slopes, the overflow diversion could be inoperative during peak storms.

Green Hill Pond Dam was neither designed nor constructed according to current state-of-the-art procedures. There are areas of concern which must be corrected to assure the continued performance of this dam. This conclusion is based upon the visual inspection at the site, the limited engineering data, and limited evidence of operational and maintenance procedures. Generally,

the dam is in good condition although the outlets to the spillway and overflow diversion are in poor condition. Green Hill has been classified in the "high" hazard category.


The following are visible signs of distress which indicate a potential hazard at the site: blockage of the shaft of the spillway, blockage of the overflow diversion, leakage through the walls of the spillway, misalignment of the stone block forming the western half of the spillway, siltation of the outlet conduit at 121 feet and 573 feet downstream of the dam, erosion and lack of riprap on the upstream face of the dam, erosion due to surface runoff on the downstream face of the dam, accumulation of surface runoff in the playground area at the toe of the dam, and erosion of the trash gate and the concrete on the intake box of the diversion conduit.

Hydraulic analyses indicate that the spillway at the dam can discharge a flow of 33 cfs at El 653 which is the average elevation of the crest of the dam. An inflow test flood of 280 cfs will overtop the main dam by an average of 0.2 feet. These calculations are based on an unobstructed flow through the spillway and do not consider overflow through the diversion. In the event of overtopping, complete failure of the dam is unlikely to occur. However, erosion of the dam could occur resulting in a breach and partial failure of the dam.

It is recommended that the Owner accomplish the following: remove debris from the shaft of the spillway and from the overflow diversion, install a trash rack on the spillway and repair the trash rack on the overflow diversion, construct an overflow spillway, construct a gated outlet, repair leakage and the misaligned slab at the weir of the spillway, clean accumulated silt out of the outlet conduit, repair erosion on the upstream face of the dam and protect the slope with riprap, construct a swale to prevent surface runoff from eroding the downstream face of the dam and collecting in the area at the toe of the dam, and repair the concrete on the intake of the diversion conduit. The Owner should also implement a systematic program of inspection and maintenance.

The debris in the spillway and in the overflow diversion should be removed within 30 days. The remaining recommendations and remedial measures outlined above and in Section 7 should be implemented

by the Owner within a period of 2 years after receipt of this Phase I Inspection Report. An alternative to these recommendations would be to drain the pond and breach or remove the dam.



A handwritten signature in cursive script, appearing to read "Edward M. Greco".

Edward M. Greco, P.E.
Project Manager
Metcalf & Eddy, Inc.

Connecticut Registration
No. 08365

Approved by:

A handwritten signature in cursive script, appearing to read "Stephen L. Bishop".

Stephen L. Bishop, P.E.
Vice President
Metcalf & Eddy, Inc.

Massachusetts Registration
No. 19703



This Phase I Inspection Report on Green Hill Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division




FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division



SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in Recommended Guidelines for Safety Inspection of Dams, for a Phase I Investigation. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrology and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general conditions and the downstream damage potential.

TABLE OF CONTENTS

	<u>Page</u>
BRIEF ASSESSMENT	
PREFACE	
OVERVIEW PHOTO	
LOCATION MAP	111
REPORT	1v
SECTION 1 - PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	2
1.3 Pertinent Data	5
SECTION 2 - ENGINEERING DATA	10
2.1 General	10
2.2 Construction Records	11
2.3 Operation Records	11
2.4 Evaluation of Data	11
SECTION 3 - VISUAL INSPECTION	12
3.1 Findings	12
3.2 Evaluation	14
SECTION 4 - OPERATION PROCEDURES	15
4.1 Procedures	15
4.2 Maintenance of Dam	15
4.3 Maintenance of Operating Facilities	15
4.4 Description of Any Warning System in Effect	15
4.5 Evaluation	15
SECTION 5 - HYDRAULIC/HYDROLOGIC	16
5.1 Evaluation of Features	16

TABLE OF CONTENTS (Continued)


	<u>Page</u>
SECTION 6 - STRUCTURAL STABILITY	18
6.1 Evaluation of Structural Stability	18
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES	20
7.1 Dam Assessment	20
7.2 Recommendations	21
7.3 Remedial Measures	21
APPENDIXES	
APPENDIX A - PERIODICAL INSPECTION CHECKLIST	
APPENDIX B - PLAN OF DAM AND PREVIOUS INSPECTION REPORTS	
APPENDIX C - PHOTOGRAPHS	
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	

**OVERVIEW
GREEN HILL POND
WORCESTER, MASSACHUSETTS**



VIEW FROM EAST ABUTMENT

**Location and Direction of Photographs
Shown on Figure in Appendix B**



LOCATION MAP - GREEN HILL POND

NATIONAL DAM INSPECTION
PROGRAM

PHASE I INSPECTION REPORT

GREEN HILL POND

SECTION 1

PROJECT INFORMATION

1.1 General

- a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Metcalf & Eddy, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed was issued to Metcalf & Eddy, Inc. under a letter of May 3, 1978, from Ralph T. Garver, Colonel, Corps of Engineers. Contract No. DACW 33-78-C-0306 has been assigned by the Corps of Engineers for this work.
- b. Purpose
 - (1) Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
 - (2) Encourage and assist the States to initiate quickly effective dam safety programs for non-Federal dams.
 - (3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

- a. Location. The dam is located on the headwaters of Hermitage Brook, a tributary of the Blackstone River, in the City of Worcester, Worcester County, Massachusetts (see Location Map).
- b. Description of Dam and Appurtenances. Green Hill Pond dam is an earth fill dam about 200 feet long with a maximum height of 20 feet (see Plan of Dam and Sections, Figures B-1 and B-2). The embankment is founded on bedrock and is constructed of a stone masonry core wall 5 feet thick at the bottom, 2 feet thick at the top, and 17 feet high (see Figure B-4). The remainder of the embankment is earth fill. The crest of the dam is generally about 30 feet wide but increases to about 100 feet wide at the west abutment. The elevation (El) of the crest varies from 652.5 to 654.0. A paved road, Green Hill Parkway, is located on the crest. The upstream slope is 7:1 and is a sandy beach. The downstream slope is 5:1 and is covered with grass.

A vertical shaft spillway is located near the midpoint of the dam. It consists of a 23.6 feet long (side to side) granite overflow weir and a 3.6 by 25.6 foot (inside dimensions) vertical stone shaft with 2.7 foot thick walls. The crest of the spillway is at El 651.0. The shaft descends about 17.4 feet to an invert at El 633.6 and connects with the outlet conduit which is perpendicular to the dam (see Figure B-3). A stone headwall which was part of the original dam may still be located below the ground surface downstream of the spillway (see Figure B-4).

Water over the spillway discharges about 573 feet downstream of the upstream face of the dam. Manholes are located 121 feet, 306 feet, and 424 feet along the outlet conduit from the spillway (see Figure B-2). At the upstream end of the first manhole, the conduit is 18-inch diameter reinforced concrete pipe. From the downstream end of the first manhole to the

outlet, the conduit is 30-inch diameter reinforced concrete pipe. The size of the outlet from the spillway to the 18-inch diameter pipe is unknown. Drawings (Figures B-3 and B-4) indicate that there is a 38-foot-long approach channel on the bottom of the pond which leads to a 1.3-foot-wide by 4.5-foot-high opening at the base of the stone shaft of the spillway. This opening leads to a box conduit which passes beneath the shaft and the wall of the old dam and enters a 3.8-foot-wide by 7-foot-high stone horseshoe-shaped tunnel. The transition from this old conduit to the 18-inch diameter reinforced concrete pipe is unknown. The invert of the 18-inch pipe is at El 636.6 at the first manhole. The invert of the 30-inch pipe is El 633.0 at the outlet.

An overflow diversion structure is located at the northeast end of Green Hill Pond (See Location Map). Flow from this diversion is to Coal Mine Brook, about 0.4 miles to the northeast (see Figure B-5). The diversion conduit is a 30-inch diameter concrete pipe which leads to a 48-inch diameter tunnel beneath Green Hill, discharging to various smaller pipes downstream. The inlet to the conduit is a concrete box with a 1.6-foot-high by 12-foot-long opening on the upstream face. The overflow weir to the conduit is at El 650.9.

- c. Size Classification. Green Hill Pond Dam is classified in the "small" category since it has a maximum height of 20 feet and a maximum storage capacity of 300 acre-feet.
- d. Hazard Classification. Immediately downstream of the dam is a public park and playground. Thickly developed commercial and residential areas of Worcester are located in the downstream valley about 0.3 miles from the dam. Memorial Hospital is also located 0.7 miles downstream in the valley. In the event of dam failure, more than a few lives could be lost and extensive property damage could occur.

A 12-foot-high, abandoned dam located 1,300 feet below Green Hill Pond may impede some flood flows. However, the condition and stability of that dam is unknown. Accordingly, Green Hill Pond Dam has been classified in the "high" hazard category. A 1973 inspection report by the Massachusetts Department of Public Works indicates there is no risk to life and property.

- e. Ownership. The dam is presently owned by the Worcester Department of Public Works, 30 E. Worcester Street, Worcester, Massachusetts 01604. Mr. F. Worth Landers, Commissioner (617-798-8151) granted permission to enter the property and inspect the dam.
- f. Operator. There are no known operators of the dam since there are no operational features.
- g. Purpose of Dam. The dam was originally constructed by the Green family at their estate for recreational and aesthetic purposes. In about 1905, the estate was given to the City of Worcester. The pond was used for swimming until about 1955. After that time records indicate the water became polluted from the cesspool for the bathhouse and from livestock grazed nearby. Since 1955, the pond has not been suitable for swimming. The adjoining land is utilized for a playground, picnic area, and a golf course.
- h. Design and Construction History. The original dam, shown on the 1881 drawings as the "old dam" (see Figure B-3), was probably built around 1850 and is presumably still in place below the ground surface. Drawings indicate it consists of a 14.5 foot high, 10.5 foot thick vertical stone wall with an outlet conduit at the base which lead to a 3.8 foot wide by 7 foot high (inside dimensions) stone horseshoe-shaped tunnel (see Figures B-3 and B-4).

About 1881, Martin Green designed changes to the dam which presumably were built a short time later. These changes included construction of the vertical shaft spillway, reconstruction of the embankment with a stone core

wall, and extension of the outlet conduit upstream, including a slide gate and an approach channel. About 1905, the dam and part of the Green family estate were given to the City of Worcester.

An inspection report written in 1938 stated that the slide gate to the outlet was broken and inoperable and a fish screen was on the spillway weir. After the 1936 floods, the overflow diversion was constructed by the City of Worcester. Also, some time between 1955 and 1965, the area below the toe of the dam was filled in to make a playground, and the outlet conduit was extended to its present location.

- i. Normal Operational Procedures. There are no normal operating procedures at this dam. There is no apparent outlet control, and it appears that the approach to the outlet conduit is filled with sand. However, a flow of 5 to 10 gallons per minute is discharging from the downstream end of the conduit.

The spillway for Green Hill Pond is ungated and flows are unrestricted, although the vertical shaft is blocked with debris.

The overflow diversion is also uncontrolled, and the opening to the 30-inch conduit is filled with debris.

1.3 Pertinent Data

- a. Drainage Area. The approximately 136-acre (0.21 square mile) drainage area above the dam consists of a park and golf course. The land is sparsely developed, mostly grassed, and has moderate slopes. Discharge is to Hermitage Brook, which flows to a 12 foot high abandoned dam located about 1,300 feet downstream of Green Hill Pond. Some flow appears to enter a 2.6 foot high by 5.3 foot wide box conduit at the dam and could not be detected further downstream. Residential areas are situated 150 feet downstream of the abandoned dam, and the valley continues approximately along Hooper Street into downtown Worcester.

- b. Discharge at Dam Site. Water discharges from the pond through an 18-inch and a 30-inch diameter, reinforced concrete outlet conduit. Drawings indicate that flow into the conduit is through the 25.6-foot by 3.6-foot vertical shaft of the spillway and from a 1.3 foot by 4.5-foot slide gate opening at the bottom of the upstream wall of the shaft. Presently, debris is blocking the shaft, and sand has accumulated upstream of the gate opening. Both the spillway and the opening are uncontrolled. The outlet conduit discharges 573 feet downstream, at an invert elevation of 633.0. The lower 452 feet of conduit has a 0.2 to 1.3 percent slope.

The pond can also overflow through a 30-inch diameter diversion conduit located at the opposite end of the pond from the dam. The conduit has a 1.6-foot by 12-foot intake opening with an overflow elevation of 650.9. The conduit has a slope of about 0.4 percent.

Hydraulic analyses indicated that the spillway can discharge an estimated 33 cfs at El 653 which is an average elevation of the crest of the dam. An inflow test flood of 280 cfs (half of the probable maximum flood) will overtop the main dam by an average of 0.2 feet. These calculations do not take into consideration the discharge into the overflow diversion which is presently blocked with debris. Due to downstream pipe sites and slopes, the overflow diversion could be inoperative during peak storms even after the debris is cleared.

The maximum flood at the dam site is unknown; but personnel at the Worcester Parks Department recall the dam being overtopped with flow over Green Hill Parkway.

- c. Elevation (feet above Mean Sea Level (MSL)). A benchmark at El 651.0 was established at the spillway crest. The elevation was estimated from a U.S.G.S. topographical map.

- (1) Top dam 652.5 to 654.0
- (2) Test flood pool: 653.2
- (3) Design surcharge (original design):
unknown
- (4) Full flood control pool: Not Applicable
(N/A)
- (5) Recreation pool: 650.9 overflow diversion
651.0 spillway crest
- (6) Spillway crest (ungated): 651.0
- (7) Upstream portal invert diversion tunnel:
650.9
- (8) Stream bed at centerline of dam: 633.9
- (9) Maximum tailwater: None

d. Reservoir

- (1) Length of maximum pool: 2,400 feet
- (2) Length of recreation pool: 2,400 feet
- (3) Length of flood control pool: N/A

e. Storage (acre feet)

- (1) Test flood surcharge: 60 at El 653.9
- (2) Top of dam: 300
- (3) Flood control pool: N/A
- (4) Recreation pool: 250 (Approximate)
- (5) Spillway Crest: 250

f. Reservoir Surface (acres)

- *(1) Top dam: 27
- *(2) Maximum pool: 27
- (3) Flood-control pool: N/A
- (4) Recreation pool: 27
- (5) Spillway crest: 27

g. Dam

- (1) Type - earthfill
- (2) Length - 200 feet
- (3) Height - maximum 20 feet
- (4) Top width: 30 to 100 feet
- (5) Side slopes - upstream 7:1; downstream 5:1
- (6) Zoning: Unknown
- (7) Impervious core: Stone masonry core wall
- (8) Cutoff: Unknown, bedrock foundation
- (9) Grout curtain: Unknown

i. Spillway

- (1) Type: overflow weir with vertical shaft
- (2) Length of weir: 23.6 feet
- (3) Crest elevation: 651 MSL (assumed benchmark)
- (4) Gates: None

*Based on the assumption that the surface area will not significantly increase with changes in reservoir elevation from 651.0 to 653.0.

(5) Upstream Channel: None

(6) Downstream Channel: 25.6 feet by 3.6 feet
vertical stone shaft to outlet conduit

- j. Regulating Outlets. The regulating outlet at the dam is an 18-inch and a 30-inch diameter reinforced concrete pipe which are ungated.

Discharge is presently flowing at 5 to 10 gpm from the downstream end of the pipe. The source of this flow is unknown, but could be from the shaft of the spillway and/or from the intake of the conduit. There is no apparent control of this outlet.

The pond level is also regulated by a side inlet box spillway which discharges to a 30-inch diameter diversion conduit located at the northeast end of the pond. This inlet is not controlled. The pond level is below the overflow level at the present time.

SECTION 2

ENGINEERING DATA

- 2.1 General. The only plans, specifications, or computations available from the Owner, State, or County offices relative to the design and construction of this dam are: two sheets of drawings dated May 10, 1881 showing the original dam and proposed reconstruction (copies in Appendix B); and three undated drawings for the overflow diversion (copy of Sheet No. 1 in Appendix B). The only other data available for this evaluation were visual observations made during inspection, review of a previous inspection report, and conversations with personnel at the Worcester Department of Public Works (Owner of the dam), the Worcester Parks Department, and State and County agencies.

We acknowledge the assistance and cooperation of personnel of the Massachusetts Department of Public Works: Messrs. Willis Regan and Raymond Rochford, and of the Massachusetts Department of Environmental Quality Engineering, Division of Waterways: Messrs. John J. Hannon and Joseph Iagallo.

Also, we acknowledge the cooperation and assistance of personnel from the Worcester County Engineer's Office: Messrs. John O'Toole, Joseph Brazauskas, and Mr. Wallace Lindquist - recently retired from county service.

In addition, we thank Mr. F.W. Landers, Commissioner, Worcester Department of Public Works, who allowed us to inspect the dam. We also thank Messrs. Richard Grant and Edward Mara of the Worcester Department of Public Works, and Tom Taylor of the Worcester Parks Department, each of whom researched their files for information on the dam.

- 2.2 Construction Records. There are no detailed construction records available.
- 2.3 Operation Records. No operation records are available, and there is no daily record kept of the elevation of the pool or rainfall at the dam site.
- 2.4 Evaluation
- a. Availability. Due to the age of this dam, there is limited engineering data available.
 - b. Adequacy. The lack of in-depth engineering data did not allow for a definitive review. Therefore the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, past performance history and sound engineering judgment.
 - c. Validity. The limited engineering data available is valid.

SECTION 3

VISUAL INSPECTION

3.1 Findings

- a. General. The Phase I Inspection of the dam at Green Hill Pond was performed on July 31, 1978. A copy of the inspection check list is included in Appendix A. Previous inspections of this dam have been made by others since 1938. A partial listing of these inspections is in Appendix B. An inspection was made in 1973 by personnel from the Massachusetts Department of Public Works. A copy of their report is included in Appendix B.
- b. Dam. Green Hill dam is an earth fill embankment with a stone masonry core wall. The dam is generally in good condition. No seepage was noted at the dam. The slopes of the dam are flat and clear of trees. The crest is mostly a paved roadway. Two signs of distress were observed at the site. First, erosion has occurred on the upstream face of the dam near the west abutment. Sand has been washed away around the concrete slabs in the picnic areas. The slabs are cracked and settled. There are no signs of riprap protection on the upstream face of the dam. Secondly, surface runoff from Green Hill Parkway, which collects near the midpoint of the dam, has eroded a gully in the downstream face. This runoff combines with runoff from the hillside east of the dam and forms large puddles of water in the playground area downstream of the toe of the dam.
- c. Appurtenant Structures. The spillway is a vertical stone shaft with a granite overflow weir. The structure is in poor condition. Water is flowing under the granite weir and into the shaft. The piece of granite on the west half of the weir is misaligned. The shaft is filled with soil and debris to within 2 feet of the crest of the weir. This obstruction restricts all flows over the spillway. There is a fence located upstream of the crest of the spillway.

The outlet conduit extends 573 feet from the upstream face of the shaft of the spillway to the outlet. The upstream approach area appears to be completely filled with sand. The condition of 121 feet of the conduit under the dam is unknown. Sediment has accumulated to a depth of 0.5 feet at the bottom of the first manhole located 121 feet downstream. The conduit appears to be blocked between the first and second manholes. The outlet end of the conduit contains a build-up of sediment 0.9 feet thick at the invert of the pipe.

The overflow diversion structure is located at the northeast end of the pond and has a concrete box intake with a trash rack. The conduit is completely blocked with leaves, trash, and other debris. This material passed through the 6-inch openings of the trash rack and through an opening on the top of the intake box. The trash rack is severely corroded. Erosion of the concrete has also taken place on the upstream face of the intake box.

- d. Reservoir Area. The area around Green Hill Pond is a park and golf course. There are a few buildings, such as a club house and maintenance buildings, but no residences. It is unlikely that significant development will occur in the future. The area is grassed and wooded and has moderate slopes of 10 to 20 percent.
- e. Downstream Channel. Discharge from the outlet flows about 700 feet downstream in a natural stream bed which slopes at about 2 percent. At that point, water enters a 5.3-foot-wide by 2.6-foot-high concrete box conduit which is part of a 12 foot high abandoned dam. The outlet to the conduit was not visible. Flow may continue downstream in the natural stream bed. The valley continues at a slope of 3 percent into residential and commercial areas of downtown Worcester.

3.2 Evaluation. Although the dam appears to be in good condition, the two outlets of the dam are blocked and the outlet conduit from the spillway is partially filled with silt. It is evident that these structures are not adequately maintained. Recommended measures to improve these conditions are stated in Section 7.3.

SECTION 4

OPERATIONAL PROCEDURES

- 4.1 Procedures. There are no operational procedures at this dam.
- 4.2 Maintenance of Dam. An office of the Worcester Parks Department is located near the dam. However, the outlets for the dam are not adequately maintained. Some maintenance to the dam has occurred since the spring, such as repair of erosion from surface runoff on the downstream face of the dam and around the stone wall of the spillway. However, the spillway, the outlet conduit, and the diversion conduit are all blocked with debris. The 1973 inspection report prepared by the Massachusetts Department of Public Works (see copy in Appendix B) recommended that debris be cleared from the spillway.
- 4.3 Maintenance of Operational Facilities. Only the downstream end of the outlet conduit was visible during inspection. The end of the pipe is filled in with silt to a depth of 0.9 feet. The condition of the intake was not visible, since it is apparently plugged. The overflow diversion is plugged with leaves, wood, and trash.
- 4.4 Description of Any Warning Systems in Effect. There are no warning systems in effect at this dam.
- 4.5 Evaluation. There are no operational or warning systems in effect at Green Hill Dam, and the maintenance is inadequate. This is extremely undesirable, considering the dam is in the "high" hazard category. A program of operation and maintenance for this dam should be implemented as recommended in Section 7.3.

SECTION 5

HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

- a. Design Data. The probable maximum flood (PMF) rate was determined to be 2,650 cfs per square mile. This calculation is based on an average drainage area slope of 11 percent, the pond-plus-swamp area to drainage area ratio of 23.8 percent, and the U.S. Army Corps of Engineers' Flow Rates (dated December 1977). Applying one-half the PMF to the 0.21 square miles of drainage area results in a calculated peak flow of 280 cfs as the inflow test flood. By adjusting the inflow test flood for surcharge storage, the maximum discharge at the spillway was established as 92 cfs with a water surface at El 653.2.

An overflow diversion structure at the north-east end of Green Hill Pond was not included in these calculations. The structure consists of a 30-inch diameter pipe having an overflow at El 650.9. Outflow from Green Hill Pond would be through this structure before discharging over the spillway. However, because the pipe was obstructed with debris, it is inoperative. Furthermore, due to downstream pipe sizes and slopes, the overflow diversion could be inoperative during peak storms, even after the debris is cleared. All calculations are therefore based on the overflow diversion being inoperable.

Flow over the crest of the dam is predicted to be 58 cfs while flow over the main spillway would be 34 cfs. The discharge over the spillway is controlled by the 18-inch outlet pipe downstream of the spillway. The maximum head on the dam would be 0.7 feet with a discharge of 1.5 cfs per foot of width. The depth of water over the dam at critical flow would be at 0.4 feet with a velocity of 3.6 fps.

- b. Experience Data. Hydraulic records are not available for this dam. Personnel at the Green

Hill office of the Worcester Parks Department recall that in 1955 the dam was overtopped and that flow was over Green Hill Parkway.

- c. Visual Observations. Normal discharge from Green Hill Pond is over the main spillway and through an overflow diversion structure at the northeast end of Green Hill Pond. The flow over the spillway before overtopping is controlled by an 18-inch pipe. The overflow diversion structure upstream was partially filled with leaves, silt, and debris and discharge was totally restricted. The trash rack was severely corroded.
- d. Overtopping Potential. Overtopping of the dam is expected under the inflow test flood of 280 cfs. Discussion with Personnel from the Worcester Parks Department indicated that the dam was overtopped during the 1955 flood. In the event of overtopping, complete failure of the dam is unlikely to occur. However, erosion of the dam could occur resulting in a breach or partial failure of the dam.

A flood wave due to dam failure would have a height of 4.0 feet at a velocity of 14 fps.

SECTION 6

STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

- a. Visual Observations. The evaluation of the structural stability of Green Hill Pond Dam is based on the visual inspection conducted on July 31, 1978. As discussed in Section 3, Visual Inspection, the embankment of the dam is generally in good condition, although the shaft of the spillway, the outlet conduit, and the diversion conduit are blocked.

Based on these observations the embankment of the dam is not a potential hazard, however, blockage of the spillway and the overflow diversion is a serious hazard.

- b. Design and Construction Data. There are two drawings dated 1881 available from the County on the design and construction of this dam (see Figures B-3 and B-4). There are also three drawings available from the City on the design and construction of the diversion conduit (Sheet No. 1 is included as Figure B-5). There are no other plans, specifications or computations available on the design, construction, or repair of this dam from the Owner, County, or State officers. Furthermore, information does not appear to exist on the type, shear strength, and permeability of the soil and/or rock materials of the embankment.

Green Hill Pond Dam was originally built about 1850 and was reconstructed about 1881. Drawings indicate the embankment contains a 17-foot- high, tapered stone masonry core wall, 5 feet thick at the base and 2 feet thick at the top (see Figure B-4). The remainder of the embankment is earth fill. The dam is shown on the drawings to be founded on bedrock.

- c. Operating Records. There is no evidence of instrumentation of any type in Green Hill Pond Dam, and there is nothing to indicate that any instrumentation was ever installed in this dam. The performance of this dam under prior loading can only be inferred by physical evidence at the site.
- d. Post-Construction Changes. There are no as-built drawings available for Green Hill Pond Dam. The drawings dated 1881 show some of the original 1850 dam. The outlet of the conduit was extended from a point 75.5 feet downstream to a point 573 feet downstream. The location and type of transition from the old outlet conduit under the dam to the 18-inch outlet pipe is unknown.

An overflow diversion structure was also constructed at the northeast end of the pond. This was probably built sometime after the 1936 storms.

- e. Seismic Stability. The dam is located in Seismic Zone No. 2 and in accordance with Phase I "Recommended Guidelines" does not warrant seismic analyses.

SECTION 7

ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment

- a. Condition. Green Hill Pond Dam was neither designed nor constructed according to current state-of-the-art procedures. Based upon the visual inspection of the site, the limited engineering data and a lack of operational or maintenance information, there are areas of concern which must be corrected to assure the continued performance of this dam. Generally, the dam is considered to be in good condition although the outlets to the spillway and overflow diversion structure are in poor condition. Several signs of distress were observed at the site: blockage of the shaft of the spillway and the diversion conduit; leakage through the walls of the spillway; misalignment of the stone block forming the western half of the spillway weir; silt deposited in the outlet conduit at the upstream manhole and at the downstream end; erosion and lack of riprap on the upstream face of the dam; erosion due to surface runoff on the downstream face of the dam; poor drainage of the playground area at the toe of the dam; and corrosion of the trash rack and spalling of the concrete intake on the diversion conduit.

Hydraulic analyses indicate that the spillway can discharge a flow of 33 cfs at El 653 which is an average elevation of the crest of the dam. An inflow test flood at 280 cfs (half of the probable maximum flood) will overtop the dam by an average of 0.2 feet. This calculation is based on an unobstructed flow into the spillway, which is presently blocked, and does not consider discharge through the overflow diversion which is blocked and may be inoperative during peak flows. Previous experience indicates the dam was overtopped in the 1955 floods.

- b. Adequacy. The lack of in-depth engineering data did not allow for a definitive review. Therefore the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, past performance history and sound engineering judgment.
- c. Urgency. The recommendations and remedial measures outlined below should be implemented by the Owner within 2 years after receipt of this Phase I Inspection Report. However, clearing of the debris from the spillway and from the overflow diversion facilities should be done within 30 days.
- d. Need for Additional information. Additional investigations to further assess the adequacy of the dam are outlined below in Section 7.2. Recommendations.

7.2 Recommendations. In view of the concerns over the continued performance of the dam and spillway, it is recommended that the Owner employ a qualified consultant to:

- a. conduct a more detailed field investigation of the spillway outlet and the overflow system.
- b. conduct a more detailed hydrologic and hydraulic investigation of the spillway and overflow diversion.

The recommendations on repairs and maintenance procedures are outlined below under Section 7.3, Remedial Measures.

7.3 Remedial Measures

- a. Alternatives. An alternative to implementing the recommendations listed above and the maintenance procedures itemized below would be to drain the pond and breach or remove the dam.
- b. Operating and Maintenance Procedures. The dam and appurtenant structures are not adequately maintained. It is recommended that the Owner accomplish the following:

- (1) remove all debris from the shaft of the spillway and the overflow diversion facilities
- (2) install a trash rack on the spillway and repair the trash rack on the overflow diversion
- (3) construct a gated outlet
- (4) repair the weir of the spillway where water is flowing beneath the granite slabs and realign the western weir stone.
- (5) clean accumulated silt out of the man-holes and outlet conduits
- (6) repair erosion on the upstream face of the dam and protect the slope with riprap
- (7) construct a swale along Green Hill Parkway such that surface runoff does not erode the downstream face of the dam and collect in the area of the toe of the dam
- (8) construct a swale such that surface runoff from the downstream side slopes does not collect and form wet areas below the toe of the dam
- (9) repair the concrete on the intake of the diversion conduit
- (10) implement a systematic program of maintenance inspections. As a minimum, the inspection program should consist of a monthly inspection of the dam and appurtenances, supplemented by additional inspections during and after severe storms. The spillway and the overflow diversion should be examined at that time. All repairs and maintenance should be undertaken in accordance with all applicable State regulations
- (11) periodic technical inspections of this dam should be continued on a bi-annual frequency

- (12) institute a definite plan for surveillance and a warning system during periods of unusually heavy rains and/or runoff.

APPENDIX A
PERIODIC INSPECTION CHECKLIST

PERIODIC INSPECTION

PARTY ORGANIZATION

PROJECT Green Hill Pond

DATE 7/31/78

TIME 8:00 AM - 1:00 PM

WEATHER partly cloudy - 75°F

W.S. ELEV. 650.3 U.S. 633.9 DN.S.

* assumed benchmark elevation 651.0
on top of spillway weir - from USGS
topographic quadrangle

PARTY:

1. Mike Larson

6. _____

2. Ed Greco

7. Sue Pierce

3. Lyle Branagan

8. Lou Taverna

4. Dick Weber

9. David Cole

5. Carol Sweet

10. _____

PROJECT FEATURE

INSPECTED BY

REMARKS

1. dam embankment

Larson + Greco

2. spillway

Branagan

3. outlet conduit

Branagan + Larson

4. diversion conduit

Larson + Weber

5. _____

6. _____

7. _____

8. _____

9. _____

10. _____

PERIODIC INSPECTION CHECK LIST

PROJECT Green Hill Pond

DATE 7/31/78

PROJECT FEATURE dam embankment

NAME Mike Larson

DISCIPLINE geotechnical

NAME Ed Greco

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	<u>crest-paved asphalt road; grass + beach on up face; grass on down face</u>
Crest Elevation	<u>varies from 652.5 to 654.0</u>
Current Pool Elevation	<u>650.3</u>
Maximum Impoundment to Date	<u>unknown</u>
Surface Cracks	<u>alligator cracking on pavement of east abutment</u>
Pavement Condition	<u>poor</u>
Movement or Settlement of Crest	<u>none visible</u>
Lateral Movement	<u>none visible</u>
Vertical Alignment	<u>relatively flat</u>
Horizontal Alignment	<u>concave toward pond</u>
Condition at Abutment and at Concrete Structures	<u>right abutment-ties into natural hillside left abutment- bedrock outcrops</u>
Indications of Movement of Structural Items on Slopes	<u>none visible</u>
Trespassing on Slopes	<u>people in park</u>
Sloughing or Erosion of Slopes or Abutments	<u>no sloughing erosion - two areas on left side of dam, several pits + 1 gulley at 20' right of dam</u>
Rock Slope Protection - Riprap Failures	<u>no riprap, a few cut stones on both sides of spillway, shoreline receding due to wave erosion</u>
Unusual Movement or Cracking at or near Toes	<u>None visible</u>
Unusual Embankment or Downstream Seepage	<u>None visible</u>
Piping or Boils	<u>None visible</u>
Foundation Drainage Features	<u>None visible</u>
Toe Drains	<u>None visible</u>
Instrumentation System	<u>None</u>

PERIODIC INSPECTION CHECK LIST

PROJECT Green Hill PondDATE 7/31/78PROJECT FEATURE SpillwayNAME Lyle BranaganDISCIPLINE geotechnicalNAME Mike Larson

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	None
General Condition	N/A (not applicable)
Loose Rock Overhanging Channel	N/A
Trees Overhanging Channel	N/A
Floor of Approach Channel	N/A
b. Weir and Training Walls	granite slab overflow weir - granite slabs around top of vertical discharge shaft
General Condition of Concrete	poor
Rust or Staining	none
Spalling	west piece of granite slab weir has shifted out of place
Any Visible Reinforcing	none
Any Seepage or Efflorescence	water entering discharge shaft from underneath spillway weir
Drain Holes	none
c. Discharge Channel	vertical drop shaft - ^{mortared} stone walls
General Condition	very poor - filled with soil + trash to within 2 ft of crest
Loose Rock Overhanging Channel	loose slab on weir
Trees Overhanging Channel	none
Floor of Channel	not visible
Other Obstructions	none

PERIODIC INSPECTION CHECK LIST

PROJECT Green Hill Pond
 PROJECT FEATURE diversion conduit
 DISCIPLINE geotechnical

DATE 7/31/18
 NAME Mike Larson
 NAME Dick Weber

AREA EVALUATED	CONDITION
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS Intake Box a. Approach Channel	concrete box conduit with opening on upstream face
General Condition	poor - trash + debris inside box, hole in top of box, trash gate on opening eroded, concrete spalled on upstream face of box
Loose Rock Overhanging Channel	none
Trees Overhanging Channel	yes
Floor of Approach Channel	trash + debris
b. Weir and Training Walls Conduit	reinforced concrete pipe - 2.5' diameter
General Condition of Concrete	blocked with leaves, trash, and soil
Rust or Staining	none visible
Spalling	none visible
Any Visible Reinforcing	none visible
Any Seepage or Efflorescence	none visible
Drain Holes	not applicable
c. Discharge Channel	not near site
General Condition	not inspected
Loose Rock Overhanging Channel	not inspected
Trees Overhanging Channel	not inspected
Floor of Channel	not inspected
Other Obstructions	not inspected

PERIODIC INSPECTION CHECK LIST

PROJECT Green Hill Pond

DATE 7/31/78

PROJECT FEATURE outlet conduit

NAME Lyle Branagan

DISCIPLINE geotechnical

NAME Mike Larson

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	<i>submerged - not visible</i>
Slope Conditions	<i>not visible</i>
Bottom Conditions	<i>not visible</i>
Rock Slides or Falls	<i>not visible</i>
Log Boom	<i>none</i>
Debris	<i>appears to be filled with sand</i>
Condition of Concrete Lining	<i>none</i>
Drains or Weep Holes	<i>none</i>
b. Intake Structure	<i>opening at bottom of upstream wall of spillway shaft</i>
Condition of Concrete ^{Masonry}	<i>not visible</i>
Stop Logs and Slots	<i>not visible</i>

PERIODIC INSPECTION CHECK LIST

PROJECT Green Hill Pond
 PROJECT FEATURE outlet conduit
 DISCIPLINE geotechnical

DATE 7/31/78
 NAME Lyle Branagan
 NAME Mike Larson

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	1.5'dia + 2.5'dia reinforced concrete pipe pipe visible at manholes
Rust or Staining on Concrete	none visible
Spalling	none visible
Erosion or Cavitation	none visible
Cracking	none visible
Alignment of Monoliths	not visible
Alignment of Joints	not visible
Numbering of Monoliths	not visible

PERIODIC INSPECTION CHECK LIST

PROJECT Green Hill Pond
 PROJECT FEATURE outlet conduit
 DISCIPLINE geotechnical

DATE 7/31/78
 NAME Lyle Branagan
 NAME Mike Larson

AREA EVALUATED	CONDITION
OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL	
General Condition of Concrete	good
Rust or Staining	none - water clear
Spalling	slight on tip
Erosion or Cavitation	none visible
Visible Reinforcing	none
Any Seepage or Efflorescence	discharging @ 5-10 gpm
Condition at Joints	not visible
Drain Holes	not visible
Channel	overgrown swamp - grass + weeds
Loose Rock or Trees Over- hanging Channel	none significant
Condition of Discharge Channel	cluttered with grass + weeds

APPENDIX B
PLANS OF DAM AND PREVIOUS
INSPECTION REPORTS

	<u>Page</u>
Figure B-1 Plan of Dam	B-1
Figure B-2 Sections	B-2
Figures B-3 and B-4 Drawings of Dam, dated May 10, 1881	in pocket
Figure B-5 Drawing of Overflow Diversion, undated	in pocket
Previous Inspections (Partial Listing)	B-6
Inspection by Mass. Department of Public Works, dated February 5, 1973	B-7








FIGURE B-1 PLAN OF DAM



METCALF & EDDY, INC

FIGURE B-2 SECTIONS

TOWN OR CITY <i>Worcester</i> DECREE NO.		PLAN NO.	DAM NO. <i>61-23</i>
LOCATION <i>Green Hill Park</i>		C. C. DOCKET NO. <i>348 128</i>	
DESCRIPTION OF DAM		DESCRIPTION OF RESERVOIR & WATERSHED	
Type <i>Granite & Earth</i>	<i>on Solid Rock</i>	Name of Main Stream	
Length		" " any other Streams	
Height <i>20.0 ft</i>		Length of Watershed	
Thickness top		Width " "	
" bottom		Is Watershed Cultivated	
Downstream Slope <i>1 1/2:1 + to Road</i>		Percent in Forests	
Upstream " <i>2:1</i>		Steepness of Slope	<i>trace</i>
Length of Spillway <i>22'00 - 15'00 each side of gate.</i>		Kind of Soil	
Size of Gates <i>18" wide x 4'6" high.</i>		No. of Acres in Watershed	<i>0.22 Sq M</i>
Location of Gates		" " " " Reservoir	<i>27.</i>
Flashboards used		Length of Reservoir	
Width Flashboards or Gates		Width " "	
Dam designed by <i>Martin Green C.E.</i>		Max Flow Cu. Ft. per Sec.	
" constructed by		Head or Flashboards-Low Water	
Year constructed <i>1881 -</i>		" " " " -High "	
GENERAL REMARKS		GENERAL REMARKS	
<i>City of Worcester Park Dept.</i> <i>Vol. 26 P. 444 - Martin Green</i> <i>May 16, 1881</i> <i>Inspected: Nov. 17, 1938 - L.H. Spofford</i> <i>Measured: March 1, 1939 - E.S. Grover - D.F. Day.</i>			

2-1 Library Bureau 10-92208

PREVIOUS INSPECTIONS (PARTIAL LISTING)

COPY OF INSPECTION CARD ON FILE AT THE MASSACHUSETTS
DEPARTMENT OF PUBLIC WORKS, DISTRICT OFFICE, WORCESTER.

DESCRIPTION OF DAM

DISTRICT 3

Submitted by MULCAHY & DONAHUE Dam No. 3-14-348-23
 Date 2-5-73 City/Town WORCESTER
 Name of Dam GREEN HILL POND

1. Location: Topo Sheet No. 20 D

Provide 8 1/2" x 11" in clear copy of topo map with location of Dam clearly indicated.

2. Year built: _____ Year/s of subsequent repairs _____

3. Purpose of Dam: Water Supply _____ Recreational ☒ _____
 Irrigation _____ Other _____

4. Drainage Area: 122 sq. mi. _____ acres

5. Normal Ponding Area: 27 acres; Ave. depth _____

Impoundments: _____ gals.; _____ acre ft.

6. No. and type of dwellings located adjacent to pond or reservoir
NONE i.e. summer homes, etc. _____

7. Dimensions of Dam: Length 80' Max. Height 12'

Slopes: Upstream Face VERTICAL

Downstream Face 2-1

Width across top 50'

8. Classification of Dam by Material:

Earth ☒ Conc. Masonry _____ Stone Masonry ☒

Timber _____ Rockfill _____ Other _____

9. A. Description of present land usage downstream of dam:

50 % rural; 50 % urban.

B. Is there a storage area or flood plain downstream of dam which could accommodate the impoundment in the event of a complete dam failure? yes ☒ no _____

DAM NO. 3-14-348-23

10. Risk to life and property in event of complete failure.

No. of people NONE.

No. of homes NONE.

No. of Businesses NONE.

No. of industries NONE. Type _____

No. of utilities NONE. Type _____

Railroads NO.

Other dams NONE.

Other _____.

11. Attach Sketch of dam to this form showing section and plan on 8½" x 11" sheet.

12. How to locate: **FROM BELMONT ST. UP SKYLINE DRIVE**
STAY ON THIS ROAD DAM VISIBLE ON RIGHT AT
RECREATIONAL PARKING AREA.

INSPECTION REPORT - DAMS AND RESERVOIRS

1. Location: City/Town WORCESTER Dam No. 3-14-348-23
 Name of Dam GREEN HILL POND Inspected by MULCAHY & DONAHUE

Date of Inspection 2-5-73

2. Owner/s: per: Assessors _____ Prev. Inspection ✓
 Reg. of Deeds _____ Pers. Contact _____

1. CITY OF WORCESTER BUREAU OF SEWERS 20 E. WORO. ST.
 Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

2. _____
 Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

3. _____
 Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

3. Caretaker (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Name: _____ St. & No.: _____

City/Town: _____ State: _____ Tel. No.: _____

4. No. of Pictures taken NONE

5. Degree of Hazard: (if dam should fail completely)*

1. Minor ✓ 2. Moderate _____

3. Severe _____ 4. Disastrous _____

* This rating may change as land use changes (future development)

6. Outlet Control: Automatic _____ Manual _____

NONE Operative _____ yes; _____ No.

Comments:

7. Upstream Face of Dam: Conditions:

1. Good ✓ 2. Minor Repairs _____

3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

8. Downstream Face of Dam:

Condition: 1. Good ✓ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

9. Emergency Spillway: NONE

Condition: 1. Good _____ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

10. Water Level at time of inspection: 2.5 ft. above _____ below ✓
top of dam ✓ principal spillway _____
other _____

11. Summary of Deficiencies Noted:

Growth (Trees and Brush) on Embankment NONE
Animal Burrows and Washouts NONE
Damage to slopes or top of dam NONE
Cracked or Damaged Masonry NONE
Evidence of Seepage NONE
Evidence of Piping NONE
Erosion NONE
Leaks NO
Trash and/or debris impeding flow YES (IN SPILLWAY)
Clogged or blocked spillway YES
Other _____


12. Remarks & Recommendations: (Fully Explain)

*THE OVERALL CONDITION OF THIS DAM APPEARS TO BE
VERY GOOD. IT IS RECOMMENDED THAT THE SPILLWAY
BE CLEARED OF ALL DEBRIS.*

13. Overall Condition:


1. Safe ✓
2. Minor repairs needed _____
3. Conditionally safe - major repairs needed _____
4. Unsafe _____
5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

WORCESTER
GREEN HILL POND DAM
DAM No. 3-14-348-23




SECTION A-A


APPENDIX C
PHOTOGRAPHS



NO. 1 VIEW OF SPILLWAY



NO. 2 VIEW OF DEBRIS IN SPILLWAY



NO. 3 VIEW OF DOWNSTREAM DAM SLOPE



NO. 4 VIEW OF OUTLET CONDUIT

APPENDIX D
HYDROLOGIC AND HYDRAULIC
COMPUTATIONS

I Peak Inflow Test Flood & 100 Year Flood

Area of Drainage Area - 0.21 mi^2
 Area of Pond 0.05 mi^2
 No other ponds or swamps in D.A

Drain Area is 23.8% Pond

$$\text{Typ. Slope \#1} = \frac{771-651}{900} = 13.3\%$$

$$\text{Typ Slope \#2} = \frac{751-651}{1200} = 8.3\%$$

Say Average Slope = 11%

From Extended CofE. Plot for MPF-PFR, use point about 25% of dist. below "Rolling" toward "Leesville"

$$\text{P.F.R.} = 2650 \text{ cfs/mi}^2$$

For Low Dam:

$$\boxed{\text{Inflow Test Flood} = \frac{1}{2}(2650)(0.21) = 280 \text{ c.f.s.}}$$

$$\begin{aligned} \text{100 yr. flood} - \text{Ghr. rain} &= 4.7 \text{ inches} \\ \text{infiltration} &= 6(0.18) = 1.1 \text{ inches} \end{aligned}$$

$$\left(\frac{4.7-1.1}{19-1.1} \right) (560) = \underline{113 \text{ cfs} = 100 \text{ yr. Flood Peak}}$$

II Storage Functions

$$\text{Inflow Test Flood: } Q_F = 280 \left(1 - \frac{S_F}{9.5} \right)$$

$$\therefore Q = 280 - 29.5 S_F = F_{TF}$$


$$\text{100 Year Flood: } Q_F = 113 \left(1 - \frac{S_F}{4.7} \right)$$

$$\therefore Q = 113 - 24 S = F_{100}$$

S = Depth in inches on watershed related to storage on pond.; D = Pond Stor Depth in Feet

$$S = 12(D) \frac{.05}{.21} = 2.86 D$$

III Discharge, Storage & Value of Storage Functions



Old Conduit varies from 10 ft² to 30 ft². For this calc., assume old cond has trivial hydr. loss.

$$30''\phi \cdot A = 4A1ft^2; 18''\phi \cdot A = 1.767ft^2; R_{30}^{2/3} = .73; R_{18}^{2/3} = .52$$

A- Pipe Flow Relation for H_p

$$V_{30}^2 = 0.1295 V_{18}^2 \approx 0.13 V_{18}^2 \text{ Say } n = .013 \text{ for Pipe}$$

$$H_p = 1.0 h_{v_{30}} + \frac{V_{30}^2}{2g} \left[\frac{.013}{1.49(.73)} \right]^2 + (h_{v_{18}} - h_{v_{30}}) + \frac{V_{18}^2}{2g} \left[\frac{.013}{1.49(.52)} \right]^2 + h_{v_{18}}$$

$$H_p = V_{18}^2 \left[.00202 + .00839 + .01350 + 0.01047 + .01553 \right] = 0.04991 V_{18}^2$$

$$V_{18}^2 = \frac{Q_p^2}{A_{18}^2} = \frac{Q_p^2}{3.122}, \therefore \boxed{H_p = 0.016 Q_{p,pe}^2} \text{ or } \boxed{Q_p = 7.9 H_p^{1/2}}$$

$$H_p = (\text{Water Level in Ent. or in Pond}) - 635.5; \text{Max } H_p \text{ before Crest Flow} = 653.5 - 635.5$$


Water Eleu:	651	652	653	653.5	654	654.5	655
H _p	15.5	16.5	17.5	18	18.5	19	19.5
Q _p cfs	31	32	33	33.5	34	34.5	35

B- Weir flow - for 2.5' broad crest w/ correction factors & sharp edged weir "q" from "Hydraulic Tables" by William & Hazen
 $L = 24' - 0.1(4)H_w; p = 6'$

H _w	0.5'	1.0'	1.5'	2.0'	2.5'	3.0'	← Pond El. = 651.0 + H _w
Corr. Factor	0.80	0.81	0.84	0.88	0.92	0.95	
S.E. q cfs	1.21	3.36	6.20	9.62	13.59	18.06	
L	23.8	23.6	23.9	23.2	23.5	22.8	
Q _w	23	64	124	196	294	391	
H _p for Q _w	1.3'	10.0'	37.5'	93.7'	210.9'	373'	
S (D=H _w)	1.43	2.86	4.29	5.72	7.15	8.58	
Based on	F _{TF}	238	196	154	111	69	27
	F ₁₀₀	79	44	10			

C - Crest Flow

Low Pt of "Crest" = 652.5'±, but use 653 as ave. low section
 width of Crest @ El. 660 is 440'±



For Broad Crest assume $q = 2.55 H_c^{3/2}$

$Q_{c1} = 510 H_c^{1.5}$ - ignore sides beyond 200'± since depth will be low

H_c	0.2'	0.4'	0.6'	0.8'	1.0'	0.5'
Q_{c1}	46	129	237	365	510	180

IV Summary of Results (See Item V)

A. Inflow Test Flood = 280 c.f.s.

Peak Outflow = 92 c.f.s. w/ Pond El. 653.2

Max Depth on Crest = 653.2 - 652.5 = 0.7'; Max $q = 1.5$ cfs/ft

Critical Depth = $y_c = \left(\frac{(1.5)^2}{g} \right)^{1/3} = 0.4'$, $V_c = 3.6$ fps.

B. Inflow 100 Year Storm = 113 cfs.

Peak Outflow = 32 cfs. w/ Pond El. 652.2


No Flow Over Crest.


C. Max. Disch. before flow over crest = 33.4 cfs.
 This is 36% of Test Flood Outflow.

Note: A potential outlet occurs in the northeast end of Green Hill Pond. However, during peak storm flows this outlet would be an inlet, diverting flow to the pond from a street drainage system. Since the diverted area appears small, the effects of this outlet-inlet have been ignored in these calculations.

Project Nat. Review of Non-Fed. Dams Acct. No. 5864 Page 4
 Subject Worcester, Mass. Area Comptd. By LES Date 8/4/78
 Detail GREEN HILL POND DAM Cr'd. By RW Date 9/16/78

II Plot of Discharge & Storage Function vs Pond Elevation





NORTH EAST OUTLET
Profile of Disch. Pipe to Coal Mine Br.


Project Nat. Review of Non-Fed Dams **Acct. No.** 5864 **Page** 5 of 1

Subject Worcester Mass Area **Compt. By** LBJ **Date** 8/22/78

Detail GREEN HILL POND **Ckd. By** **Date**

(VI)

NORTHEAST OUTLET



Note: Bradford Ave appears removed due to constr. of I-290. Assume Sect J-K remain but K-L gone. Elev. shown here are 0.6' ± lower in value than used in Report.

METCALF & EDDY, ENGINEERS

Sect.	Size	Invert @ Entr.	Length	Slope	"Full Q" (n=.013)	Ground Elev. @ Entr.
A-B	30"	648.32	100'	.00417	26.5 cfs	650.3
B-C	48"	(647.90)	487.5	.00417	93.0	671.6
C-D	24"	645.87	163.0	.0262	36.7	670.7
D-E	18"	641.60	349.5	.06752	27.3	648.6
E-F	18"	618.0	128.0	.0367	20.1	624.3
F-G	15"	613.3	157.0	0.1274	23.1	618.8
G-H	12"	593.3	76.0	0.2632	18.3	600.0
H-I	20"	573.3	239.9	0.0554	15.0	580.2
I-J	20"	560.?	36	0.05	14.3	568.7
J-K	20"	558.2	162	.03189	11.4	565.4
K-L	20"	(553.0)	393	.03189	11.4	558 ±
End	-	540.5				543 ±

The Northeast Outlet connects the pond to a street drainage system which normally runs to Coal Mine Brook. The connection to Green Hill Pond would allow the pond to act as a temporary storm water detention basin & relieve the impact of high flow on the street drainage system. The area with drainage diverted to the pond appears minor and may be included in the estimated drainage area. This outlet would not function during peak flows - but would aid in drawing down flood storage after the peak inflow had past. A proper analysis of this "outlet" does not appear warranted or important for this Phase I Report.

(VII) Dam Failure

Crest Elev. - 651 ±

Toe Elev. 640 ±


$$Y_0 = 11'$$

Length Subject to Potential Failure = 120' ±

$$Q_p = 120 (.4) 1.68 (11)^{1.5} = 2940 \text{ cfs}$$

Vol. Stored below Crest. -


$$(\text{Est}) V_s = \frac{1}{3} (11') (.05) (640) = 117 \text{ acre feet}$$



$$A = 12.5 y^2; P \approx 25y; R = \frac{y}{2}; n = .04$$

$$S = \frac{20}{1100} = .0182; Vel = \frac{1.49}{.04} R^{2/3} (.0182)^{1/3} = 5 R^{2/3}$$

y	A	R ^{2/3}	V	Q
2	50	1	5	250
3	112.5	1.84	9.2	1033
4	200	2.83	14.1	2828
5	312.5	3.95	19.8	6176



1st Reach: 1500' to 1st Structure; $Q_p = 2940$, $y_1 = 4'$, $A_1 = 200 \text{ ft}^2$

$V_1 = 200 \times 1500 = 6.9 \text{ acre ft.}$; $V_1 < 10\% V_s$; Use Full Q_p

At 1st Structure: Flood Wave a Max. of 4' deep, traveling at 14 ± fps.

APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS



INVENTORY OF DAMS IN THE UNITED STATES

STATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	CONGR. DIST.	STATE	COUNTY	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY MO YR
MA	149	NED	MA	027	03				GREEN HILL POND DAM	4216.9	7147.0	18AUG78

POPULAR NAME	NAME OF IMPOUNDMENT
	GREENHILL POND

REGION	BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
01	06	TR-BLACKSTONE RIVER	WORCESTER	0	172300

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCT. HEIGHT (FT.)	HYDRAU. HEIGHT (FT.)	IMPOUNDING CAPACITIES	
					MAXIMUM (ACRE-FT.)	NORMAL (ACRE-FT.)
GRPEPG	1881	R	20	20	300	250

DIST OWN FED R PRV/FED SCS A VER/DATE
NED N N N N 18AUG78

REMARKS

D/S HAS	SPILLWAY			MAXIMUM DISCHARGE (FT.)	VOLUME OF DAM (CY)	POWER CAPACITY		NAVIGATION LOCKS											
	CREST LENGTH	TYPE	WIDTH (FT.)			INSTALLED (MW)	PROPOSED (MW)	NO	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)					
1	200	U	24	34	11000														

OWNER	ENGINEERING BY	CONSTRUCTION BY
CITY OF WORCESTER	MARTIN GREEN	UNKNOWN

REGULATORY AGENCY			
DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE DAY MO YR	AUTHORITY FOR INSPECTION
METCALF + EDDY, INC	31 JUL 78	PUBLIC LAW 92-367

REMARKS



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

JUN 18 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

I am forwarding to you a copy of the Green Hill Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, City of Worcester, Department of Public Works, 30 East Worcester Street, Worcester, Massachusetts 01604, ATTN: Mr. F. Worth Landers, Commissioner.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,

JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

JUN 18 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:


I am forwarding to you a copy of the Green Hill Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, City of Worcester, Department of Public Works, 30 East Worcester Street, Worcester, Massachusetts 01604, ATTN: Mr. F. Worth Landers, Commissioner.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

JUN 18 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

I am forwarding to you a copy of the Green Hill Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.


A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, City of Worcester, Department of Public Works, 30 East Worcester Street, Worcester, Massachusetts 01604, ATTN: Mr. F. Worth Landers, Commissioner.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,

Incl
As stated


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

JUN 18 1979

Mr. F. Worth Landers, Commissioner
Department of Public Works
City of Worcester
30 East Worcester Street
Worcester, Massachusetts 01604

Dear Commissioner Landers:

Forwarded herewith for your information and use is a copy of the Phase I Inspection Report on the Green Hill Pond Dam. This inspection was made under the authority of Public Law 92-367 by the firm of Metcalf & Eddy, Inc., Boston, Massachusetts under the direction and supervision of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts.

Section 7 of the report contains an evaluation and recommendations. If you have any questions concerning this report, we suggest that you contact the Department of Environmental Quality Engineering first. Then, if there are further questions contact the Project Management Branch, Engineering Division of this office. We thank you for your cooperation and assistance in carrying out this program.

Sincerely yours,

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

JUN 18 1979

Mr. F. Worth Landers, Commissioner
Department of Public Works
City of Worcester
30 East Worcester Street
Worcester, Massachusetts 01604

Dear Commissioner Landers:

Forwarded herewith for your information and use is a copy of the Phase I Inspection Report on the Green Hill Pond Dam. This inspection was made under the authority of Public Law 92-367 by the firm of Metcalf & Eddy, Inc., Boston, Massachusetts under the direction and supervision of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts.

Section 7 of the report contains an evaluation and recommendations. If you have any questions concerning this report, we suggest that you contact the Department of Environmental Quality Engineering first. Then, if there are further questions contact the Project Management Branch, Engineering Division of this office. We thank you for your cooperation and assistance in carrying out this program.

Sincerely yours,

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

JUN 18 1979

Mr. Anthony D. Cortese, Commissioner
Department of Environmental Quality
Engineering
Commonwealth of Massachusetts
100 Cambridge Street
Boston, Massachusetts 02202

Dear Commissioner Cortese:

Forwarded herewith for your information and use is a copy of the Phase I Inspection Report on Green Hill Pond Dam. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in dark ink, appearing to read "Joe E. Fryar", is written over the typed name.

JOE E. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

JUN 18 1979

Mr. Anthony D. Cortese, Commissioner
Department of Environmental Quality
Engineering
Commonwealth of Massachusetts
100 Cambridge Street
Boston, Massachusetts 02202

Dear Commissioner Cortese:

Forwarded herewith for your information and use is a copy of the Phase I Inspection Report on Green Hill Pond Dam. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in dark ink, reading "Joe E. Fryar", is positioned above the typed name and title.

JOE E. FRYAR
Chief, Engineering Division

Incl
As stated

APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS

APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS

APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS

TABLE OF CONTENTS (Continued)

	<u>Page</u>
SECTION 6 - STRUCTURAL STABILITY	18
6.1 Evaluation of Structural Stability	18
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES	20
7.1 Dam Assessment	20
7.2 Recommendations	21
7.3 Remedial Measures	21
APPENDIXES	
APPENDIX A - PERIODICAL INSPECTION CHECKLIST	
APPENDIX B - PLAN OF DAM AND PREVIOUS INSPECTION REPORTS	
APPENDIX C - PHOTOGRAPHS	
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	

TABLE OF CONTENTS (Continued)

	<u>Page</u>
SECTION 6 - STRUCTURAL STABILITY	18
6.1 Evaluation of Structural Stability	18
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES	20
7.1 Dam Assessment	20
7.2 Recommendations	21
7.3 Remedial Measures	21

APPENDIXES

APPENDIX A - PERIODICAL INSPECTION CHECKLIST

APPENDIX B - PLAN OF DAM AND PREVIOUS INSPECTION REPORTS

APPENDIX C - PHOTOGRAPHS

APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

TABLE OF CONTENTS (Continued)

	<u>Page</u>
SECTION 6 - STRUCTURAL STABILITY	18
6.1 Evaluation of Structural Stability	18
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES	20
7.1 Dam Assessment	20
7.2 Recommendations	21
7.3 Remedial Measures	21
APPENDIXES	
APPENDIX A - PERIODICAL INSPECTION CHECKLIST	
APPENDIX B - PLAN OF DAM AND PREVIOUS INSPECTION REPORTS	
APPENDIX C - PHOTOGRAPHS	
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	

This Phase I Inspection Report on Green Hill Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Charles G. Tiersch

CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division

Fred J. Ravens, Jr.

FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division

Saul Cooper

SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

This Phase I Inspection Report on Green Hill Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division




FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division



SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:




JOE B. FRYAR
Chief, Engineering Division


This Phase I Inspection Report on Green Hill Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division




FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division



SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division



INVENTORY OF DAMS IN THE UNITED STATES

STATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	CONGR. DIST.	STATE	COUNTY	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA	149	NED	MA	027	03				GREEN HILL POND DAM	4216.9	7147.0	18AUG78

POPULAR NAME	NAME OF IMPOUNDMENT
	GREENHILL POND

REGION	BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
01	06	IR-BLACKSTONE RIVER	WORCESTER	0	172300

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURAL HEIGHT (FT.)	HYDRAULIC HEIGHT (FT.)	IMPOUNDING CAPACITIES	
					MAXIMUM (ACRE-FT.)	NORMAL (ACRE-FT.)
GRREPG	1881	R	20	20	300	250

DIST OWN FED R PRV/FED SCS A VER/DATE
NED N N N N 18AUG78

REMARKS

U/S HAS	SPILLWAY			MAXIMUM DISCHARGE (FT.)	VOLUME OF DAM (CY)	POWER CAPACITY		NAVIGATION LOCKS										
	GREST LENGTH	TYPE	WIDTH (FT.)			INSTALLED (MW)	PROPOSED (MW)	NO	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)				
1	200	U	24	34	11000													

OWNER	ENGINEERING BY	CONSTRUCTION BY
CITY OF WORCESTER	MARTIN GREEN	UNKNOWN

REGULATORY AGENCY			
DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
METCALF + EDDY, INC	DAY MO YR 31JUL78	PUBLIC LAW 92-567

REMARKS



INVENTORY OF DAMS IN THE UNITED STATES

STATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	CONGR. DIST.	STATE	COUNTY	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA	149	NED	MA	027	03				GREEN HILL POND DAM	4216.9	7147.0	18AUG78

POPULAR NAME	NAME OF IMPOUNDMENT
	GREENHILL POND

REGION	BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
01	06	TR-BLACKSTONE RIVER	WORCESTER	0	172300

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURAL HEIGHT (FT.)	HYDRAULIC HEIGHT (FT.)	IMPOUNDING CAPACITIES	
					MAXIMUM (ACRE-FT.)	NORMAL (ACRE-FT.)
GRNPEG	1881	R	20	20	300	250

DIST OWN FED R PRV/FED SCS A VER/DATE
 NED N N N N 18AUG78

REMARKS

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	(14)	(15)	
D/S HAS	SPILLWAY			MAXIMUM DISCHARGE (FT.)	VOLUME OF DAM (CY)	POWER CAPACITY		NAVIGATION LOCKS							
	CREST LENGTH	TYPE	WIDTH (FT.)			INSTALLED (MW)	PROPOSED (MW)	NO.	LENGTH	WIDTH	LENGTH	WIDTH	LENGTH	WIDTH	
									(FT.)	(FT.)	(FT.)	(FT.)	(FT.)	(FT.)	(FT.)
1	200	U	24	34	11000										

OWNER	ENGINEERING BY	CONSTRUCTION BY
CITY OF WORCESTER	MARTIN GREEN	UNKNOWN

REGULATORY AGENCY			
DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
METCALF + EDDY, INC	31JUL78	PUBLIC LAW 92-567

REMARKS



INVENTORY OF DAMS IN THE UNITED STATES

STATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	CONGR. DIST.	STATE	COUNTY	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA	149	NED	MA	027	03				GREEN HILL POND DAM	4210.9	7147.0	18AUG78

POPULAR NAME	NAME OF IMPOUNDMENT
	GREENHILL POND

REGION	BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
01	06	TR-BLACKSTONE RIVER	WORCESTER	0	172300

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUC. HEIGHT (FT.)	HYDRAU. HEIGHT (FT.)	IMPOUNDING CAPACITIES
GRPEPG	1881	R	20	20	MAXIMUM (ACRE-FT.) 300 NORMAL (ACRE-FT.) 250

DIST OWN FED R PRV/FED SCS A VER/DATE
NED N N N N 18AUG78

REMARKS

D/S HAS	SPILLWAY	MAXIMUM DISCHARGE (FT.)	VOLUME OF DAM (CY)	POWER CAPACITY	NAVIGATION LOCKS
1	CREST LENGTH TYPE WIDTH (FT.) 200 U 24	34	11000	INSTALLED (MW) PROPOSED (MW)	NO LENGTH WIDTH LENGTH WIDTH LENGTH WIDTH LENGTH WIDTH (FT.) (FT.) (FT.) (FT.) (FT.) (FT.) (FT.) (FT.)

OWNER	ENGINEERING BY	CONSTRUCTION BY
CITY OF WORCESTER	MARTIN GREEN	UNKNOWN

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
METCALF + EDDY, INC	31JUL78	PUBLIC LAW 92-567

REMARKS

REFERENCE OR OFFICE SYMBOL

SUBJECT

NEDED-E

Dam Inspection Final Report

TO

FROM

DATE 8 Nov 1978 CMT 1

Chief, Design Branch
Chief, F & M Branch
Chief, Water Control Branch

Chairman,
Dam Safety Review Board

O. H. WASH

1. Attached is a single copy of the final report for
Green Hill Pond Dam, Identity No. MA00149.
2. Please ascertain that the report is acceptable in accordance with your Branch comments or instructions given to the Architect-Engineer at the Review Board Meeting.
3. If acceptable, retain the copy for your files and be prepared to sign the (master) approval sheet on 20 Nov 1978.
4. If the report requires further work or correction, notify the undersigned as soon as the determination is made.
5. The cost code for this review is ABA020700000000.

Terzian
TERZIAN

Incl
as

393

REFERENCE OR OFFICE SYMBOL

SUBJECT

NEDED-E

Dam Inspection Final Report

TO
 Chief, Design Branch
 Chief, F & M Branch
 Chief, Water Control Branch

FROM
 Chairman,
 Dam Safety Review Board

DATE 8 Nov 1978 CMT 1

1. Attached is a single copy of the final report for
Green Hill Pond Dam, Identity No. MA00149.
2. Please ascertain that the report is acceptable in accordance with your Branch comments or instructions given to the Architect-Engineer at the Review Board Meeting.
3. If acceptable, retain the copy for your files and be prepared to sign the (master) approval sheet on 20 Nov 1978.
4. If the report requires further work or correction, notify the undersigned as soon as the determination is made.
5. The cost code for this review is ABA020700000000.

Incl
 as

Terzian
 TERZIAN

Approved 11/14/78
J 2 / m only
H. Farrell McMillan

DISPOSITION FORM

For use of this form, see AR 340-15, the proponent agency is TAGCEN.

REFERENCE OR OFFICE SYMBOL

SUBJECT

NEDED-W

Review of Non-Federal Dam Inspection Draft Report

TO Chairman, Dam Safety Review
Board

FROM Chief, Water Control
Branch

DATE 26 September 1978^{CMT 1}
Mr. Manley/lab/540

NATIONAL PROGRAM OF INSPECTION OF NON-FEDERAL DAMS
DRAFT REPORT REVIEW COMMENTS
GREEN HILL POND DAM, IDENTITY NO. MA 00149
WATER CONTROL BRANCH

Page

Comments

3

Should we call this a significant to high hazard project? Your decision.

17

Delete reference to 100-year frequency flood.

D-1

When using $\frac{1}{2}$ PMF, Q out should be $280(1 - \frac{SF}{9.5})$ not $(1 - \frac{SF}{19})$. This will have some effect of F_{tf} values.

D-4

Please include assumed storage capacity curve on this plate.

General

Good report.

SARANDIS



The Commonwealth of Massachusetts

Executive Office of Environmental Affairs

Department of Environmental Quality Engineering

Division of Land and Water Use

100 Nashua Street, Boston 02114

NOTICE

City of Worcester
Department of Public Works
30 East Worcester Street
Worcester, Massachusetts 01604

Attention: Mr. F. Worth Landers, Commissioner

Dear Gentlemen:


Re: Green Hill Pond Dam #3-14-348-23

Chapter 253 of the Massachusetts General Laws Amended (Dams Safety Act), as most recently amended by Chapter 706 of the Acts of 1975, transferred jurisdiction of the "Dams-Safety Program" to the Commissioner of Environmental Quality Engineering. Included within the Act is the provision that the dam should be sufficiently strong to resist the action of the water under any circumstances which may reasonably be expected to occur. The owner of a dam could be liable for loss of life or damage to downstream property.

As the owner of the above dam in this Commonwealth, this Department alerts you to the deficiencies, recommendations, assessments and remedial measures, as cited in the report by Metcalf & Eddy, Inc., and forwarded to you by the Department of the Army, Corps of Engineers, and strongly urges that you correct the deficiencies and other related matters as soon as possible to insure the stability of the dam.

Your cooperation in this matter is anticipated and appreciated. If we can be of service to you in this connection, please feel free to contact the Division of Waterways (727-4799) at any time.

Very truly yours,



John J. Hannon, P.E.
Chief Engineer

cc: Army Corps of Engineers
District Highway Engineer
District 3

MAP:jme

3-7-80



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:

NEDED-E

6 July 1979

Mr. F. Worth Landers, Commissioner
Department of Public Works
City of Worcester
20 East Worcester Street
Worcester, MA 01604

Dear Commissioner Landers:

Inclosed for your use are three copies of the Green Hill Pond Phase I, Inspection Report as requested in your telephone conversation of 26 June with Mr. James of this office. Should you have any questions concerning this report we suggest you contact the Commonwealth of Massachusetts, Department of Environmental Quality Engineering first; then, if there are further questions contact the Project Management Branch, Engineering Division of this office.

Since these reports are in limited supply, we are requesting that upon completion of your review you return two (2) reports to this office in the pre-addressed envelope. Your cooperation in this matter is greatly appreciated.

Sincerely yours,

JOE B. FRYAR

Chief, Engineering Division

Incl
As stated

1 Ret. 11 July



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

JUN 18 1973

Mr. F. Worth Landers, Commissioner
Department of Public Works
City of Worcester
30 East Worcester Street
Worcester, Massachusetts 01604

Dear Commissioner Landers:

Forwarded herewith for your information and use is a copy of the Phase I Inspection Report on the Green Hill Pond Dam. This inspection was made under the authority of Public Law 92-367 by the firm of Metcalf & Eddy, Inc., Boston, Massachusetts under the direction and supervision of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts.

Section 7 of the report contains an evaluation and recommendations. If you have any questions concerning this report, we suggest that you contact the Department of Environmental Quality Engineering first. Then, if there are further questions contact the Project Management Branch, Engineering Division of this office. We thank you for your cooperation and assistance in carrying out this program.

Sincerely yours,

A handwritten signature in dark ink, reading "Joe B. Fryar", is positioned above the typed name.

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

JUN 13 1979

Mr. Anthony D. Cortese, Commissioner
Department of Environmental Quality
Engineering
Commonwealth of Massachusetts
100 Cambridge Street
Boston, Massachusetts 02202

Dear Commissioner Cortese:

Forwarded herewith for your information and use is a copy of the Phase I Inspection Report on Green Hill Pond Dam. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in dark ink, reading "Joe E. Fryar", is positioned above the typed name.

JOE E. FRYAR
Chief, Engineering Division

Incl
As stated